Errata

NFPA 105

Standard for the Installation of Smoke Door Assemblies and Other Opening Protectives

2007 Edition

Reference: 4.3.4 and 4.4
Errata No.: 105-07-2

The Committee on Fire Doors and Windows notes the following error in the 2007 edition of NFPA 105, *Standard for the Installation of Smoke Door Assemblies and Other Opening Protectives:*

1. Revise Section 4.4 as follows:

4.4 Labeling. Smoke door assemblies shall bear an "S" label indicating a maximum air leakage rate of ~~0.3 ft^3/min/ft^2 (0.09 m^3/min/m^2)~~ 3 ft^3/min/ft^2 (0.9 m^3/min/m^2) and the tested pressure differential of 0.1, 0.2, or 0.3 in. of water (25, 50, or 75 Pa).

Issue Date: August 23, 2007

Copyright © 2007 All Rights Reserved
NATIONAL FIRE PROTECTION ASSOCIATION

Copyright National Fire Protection Association
Provided by IHS under license with NFPA
No reproduction or networking permitted without license from IHS
Not for Resale