Errata

NFPA 105

Standard for the Installation of Smoke Door Assemblies and Other Opening Protectives

2007 Edition

Reference: 2.2 and 6.5.1
Errata No.: 105-07-01

The Committee on Fire Doors and Windows notes the following error in the 2007 edition of NFPA 105, *Standard for the Installation of Smoke Door Assemblies and Other Opening Protectives:*

1. Revise section 2.2 as follows:

2.2 NFPA Publications. National Fire Protection Association, 1 Batterymarch Park, Quincy, MA 02169-7471.
NFPA 72®, National Fire Alarm Code®, 2007 edition.
NFPA 80, *Standard for Fire Doors and Other Opening Protectives*, 2007 edition.
~~NFPA 921, *Guide for Fire and Explosion Investigations*, 2004 edition.~~
NFPA 92A, *Standard for Smoke-Control Systems Utilizing Barriers and Pressure Differences*, 2006 edition.

2. Revise section 6.5.1 as follows:
6.5.1 Smoke dampers for dedicated and non-dedicated smoke control systems shall be inspected and tested in accordance with ~~NFPA 921, *Guide for Fire and Explosion Investigations*~~ NFPA 92A, *Standard for Smoke-Control Systems Utilizing Barriers and Pressure Differences*.

Issue Date: March 23, 2007

Copyright © 2007 All Rights Reserved
NATIONAL FIRE PROTECTION ASSOCIATION

Copyright National Fire Protection Association
Provided by IHS under license with NFPA
No reproduction or networking permitted without license from IHS
Not for Resale