Errata

NFPA 30A

Code for Motor Fuel Dispensing Facilities and Repair Garages

2008 Edition

Reference: 4.2.4, 4.3.2.7(5) and 4.3.2.8
Errata No.: 30A-08-1

The Committee on Automotive and Marine Service Stations notes the following errors in the 2008 edition of NFPA 30A, *Code for Motor Fuel Dispensing Facilities and Repair Garages*.

1. Revise 4.2.4 to read as follows:

4.2.4 Where tanks are at an elevation that produces a gravity head on the dispensing device, the tank outlet shall be equipped with a device, such as a normally closed solenoid valve, positioned adjacent to and downstream from the valve specified in ~~4.3.2.5.1~~ 22.13.1 of NFPA 30, *Flammable and Combustible Liquids Code*, that is installed and adjusted so that liquid cannot

2. Revise 4.3.2.7(5) to read as follows:

(5) The tank storage complies with Chapter ~~2~~ 22 of NFPA 30, *Flammable and Combustible Liquids Code*.

3. Revise 4.3.2.8 to read as follows:

4.3.2.8 Aboveground tanks shall be provided with spill control that meets the requirements of ~~4.3.2.3~~ 21.7.1 of NFPA 30, *Flammable and Combustible Liquids Code*. Tank fill connections shall be provided with a noncombustible spill containment device.

Issue Date: March 13, 2008

(Note: Electronic products and pamphlet reprints may have this errata incorporated. For current information about the NFPA Codes and Standards, including this errata, please see www.nfpa.org/codelist)

Copyright © 2008 All Rights Reserved
NATIONAL FIRE PROTECTION ASSOCIATION

Copyright National Fire Protection Association
Provided by IHS under license with NFPA
No reproduction or networking permitted without license from IHS
Not for Resale