Errata

NFPA 407

Standard for Aircraft Fuel Servicing

2007 Edition

Reference: 5.10.1
Errata No.: 407-07-01

The Committee on Aircraft Fuel Servicing notes the following error in the 2007 edition of NFPA 407, *Standard for Aircraft Fuel Servicing*.

1. Revise 5.10.1 to read as follows:

5.10.1 Aircraft fuel servicing shall be performed outdoors. Aircraft fuel servicing incidental to aircraft fuel system maintenance operations shall comply with the requirements of NFPA ~~401~~ 410.

Issue Date: July 11, 2007

Copyright © 2007 All Rights Reserved
NATIONAL FIRE PROTECTION ASSOCIATION

Copyright National Fire Protection Association
Provided by IHS under license with NFPA
No reproduction or networking permitted without license from IHS
Not for Resale