DICOM

Release Notes for DICOM 2004



DICOM®
Digital Imaging and Communications in Medicine

Copyright National Electrical Manufacturers Association
Provided by IHS under license with NEMA
No reproduction or networking permitted without license from IHS
Not for Resale

Copyright National Electrical Manufacturers Association
Provided by IHS under license with NEMA
No reproduction or networking permitted without license from IHS
Not for Resale

Release Notes for DICOM PS 3 - 2004.

04 October 2004.

The following changes have been made relative to the published PS 3 2003 standard, by incorporating the changes specified in the supplements and correction items.

The Final Text of all applied Supplements and Correction Proposals is available at:

ftp://ftp.nema.org/medical/dicom/final/

Changes to Parts

Part 1

- Cover done 2004
- Header and footer done
- Sup 67 done (wording referenced in final text did not quite match what was in PS 3.1)
- Sup 85 done
- CP 459 done

Part 2

- Completely replace with Sup 64
-
- Sup 67 done
- Sup 85 done
- Sup 90 done
-
- CP 252 done
- CP 459 done

Part 3

- Cover done 2004
- Header and footer done
-
- Continue crusade to change “which” to “that”
- Fix various RT-related attribute tag typos
- Fix C.13.3 figures (several had extra row)
- Fix references to C.7.3.1.1.1 Modality values to always say “Defined Terms”, not sometimes “Enumerated Values”
- Restore lost Pixel Aspect Ratio figure
- Merge extra defined terms for Body Part Examined from General Series into CR Series Module

Copyright National Electrical Manufacturers Association
Provided by IHS under license with NEMA
No reproduction or networking permitted without license from IHS
Not for Resale

-
- Moved all informative annexes to Part 17
- Sup 42 done
- Sup 47 done – incorporated Window Center and Width at top level rather than nested
- Sup 58 done – and fix CTIDVol tag number to match PS 3.6 (0018,9345); correctly nest Frame Type (and amend Sup 58 FT accordingly)
- Sup 66 done
- Sup 67 done
- Sup 73 done
- Sup 84 done
- Sup 85 done
- Sup 88 done
- Sup 90 done
- Sup 91 done – including ft2
- Sup 92 done
- Sup 93 done
-
- CP 159 done
- CP 252 done – but need references for CNS and GB standards filled in
- CP 294 done
- CP 306 done
- CP 307 done – also did Table C.8-46—RT BEAMS MODULE
- CP 308 done
- CP 309 done
- CP 315 done
- CP 326 done
- CP 328 done
- CP 329 done
- CP 330 done
- CP 332 done
- CP 333 done
- CP 335 done
- CP 337 done
- CP 340 done
- CP 343 done
- CP 346 done
- CP 347 done
- CP 350 done
- CP 351 done
- CP 353 done
- CP 354 done
- CP 356 done
- CP 357 done

Copyright National Electrical Manufacturers Association
Provided by IHS under license with NEMA
No reproduction or networking permitted without license from IHS
Not for Resale

- CP 359 done
- CP 360 done
- CP 361 done
- CP 364 done
- CP 365 done
- CP 366 done
- CP 367 done
- CP 368 done
- CP 369 done
- CP 371 done
- CP 379 done
- CP 380 done
- CP 381 done
- CP 382 done
- CP 383 done
- CP 385 done
- CP 386 done
- CP 392 done
- CP 395 done
- CP 400 done
- CP 401 done
- CP 404 done
- CP 405 done
- CP 409 done
- CP 410 done
- CP 411 done
- CP 412 done
- CP 413 done
- CP 417 done
- CP 420 done
- CP 422 done
- CP 424 done
- CP 426 done
- CP 428 done
- CP 431 done
- CP 432 done
- CP 433 done – conflicted to some extent with Sup 84 – Clarification of Ultrasound Region Calibration; resolved by moving Sup 84 text rather than CP text to new location as appropriate
- CP 435 done
- CP 436 done
- CP 437 done
- CP 438 done
- CP 439 done

Copyright National Electrical Manufacturers Association
Provided by IHS under license with NEMA
No reproduction or networking permitted without license from IHS
Not for Resale

- CP 440 done
- CP 441 done
- CP 442 done
- CP 443 done
- CP 444 done
- CP 445 done
- CP 446 done
- CP 447 done
- CP 454 done
- CP 459 done

Part 4

- Sup 26 done
- Sup 47 done
- Sup 58 done
- Sup 66 done
- Sup 67 done
- Sup 73 done
- Sup 75 done
- Sup 85 done
- Sup 88 done
- Sup 90 done
- Sup 91 done
- Sup 93 done
-
- CP 268 done
- CP 309 done
- CP 326 done
- CP 334 done
- CP 336 done
- CP 340 done
- CP 342 done
- CP 344 done
- CP 348 done
- CP 376 done
- CP 397 done
- CP 407 done
- CP 422 done
- CP 459 done

Part 5

Copyright National Electrical Manufacturers Association
Provided by IHS under license with NEMA
No reproduction or networking permitted without license from IHS
Not for Resale

- Cover done 2004
- Header and footer done
-
- Tidy up quoting of transfer syntax UIDs
-
- Sup 42 done
- Sup 67 done
- Sup 85 done
-
- CP 252 done – but needs attention to Chinese font rendering
- CP 358 done
- CP 378 done
- CP 459 done

Part 6

- Cover done 2004
- Header and footer done
- Sup 42 done
- Sup 47 done
- Sup 58 done
- Sup 67 done
- Sup 73 done
- Sup 75 done
- Sup 85 done
- Sup 88 done
- Sup 90 done
- Sup 91 done
- Sup 92 done
- Sup 93 done
-
- CP 159 done
- CP 309 done
- CP 326 done
- CP 328 done
- CP 330 done
- CP 337 done
- CP 340 done
- CP 347 done
- CP 350 done
- CP 353 done
- CP 367 done
- CP 370 done
- CP 379 done
- CP 386 done

--`,,,,`,,`-`-`,,`,,`,`,,`---

Copyright National Electrical Manufacturers Association
Provided by IHS under license with NEMA
No reproduction or networking permitted without license from IHS
Not for Resale

- CP 392 done
- CP 397 done
- CP 400 done
- CP 409 done
- CP 420 done
- CP 432 done
- CP 433 done
- CP 435 done
- CP 438 done
- CP 441 done
- CP 442 done
- CP 459 done

Part 7
- Cover done 2004
- Header and footer done
-
- Sup 67 done
- Sup 85 done
- Sup 90 done
- CP 355 done
- CP 459 done

Part 8
- Cover done 2004
- Header and footer done
-
- Sup 67 done
- Sup 85 done
- Sup 90 done
- CP 459 done

Part 10
- Cover done 2004
- Header and footer done
-
- Sup 67 done
- Sup 85 done
- CP 269 done
- CP 459 done

Part 11
- Cover done 2004
- Header and footer done

Copyright National Electrical Manufacturers Association
Provided by IHS under license with NEMA
No reproduction or networking permitted without license from IHS
Not for Resale

-
- Sup 42 done
- Sup 67 done
- Sup 80 done
- Sup 82 done
- Sup 85 done
- Sup 87 done
- Sup 88 done
- Sup 92 done
-
- CP 408 done
- CP 459 done

Part 12
- Cover done 2004
- Header and footer done
-
- Sup 42 done
- Sup 67 done
- Sup 80 done
- Sup 82 done
- Sup 85 done
- Sup 87 done
- CP 459 done

Part 14
- Cover done 2004
- Header and footer done
-
- Sup 67 done
-
- CP 399 done

Part 15
- Cover done 2004
- Header and footer done
-
- Sup 58 done
- Sup 67 done
- Sup 85 done
-
- CP 338 done
- CP 341 done
- CP 421 done

Copyright National Electrical Manufacturers Association
Provided by IHS under license with NEMA
No reproduction or networking permitted without license from IHS
Not for Resale

- CP 459 done

Part 16

- Cover done 2004
- Header and footer done
- Include CP 310 Annex D definitions not included with rest of CP 310 in last edition
- Changed “CID” to “BCID” in rows 3 and 7 of TID 5204 Wall Motion Analysis per H.S.
-
- Sup 26 done – conflict with CIDs 1200xx, fixed by renaming new to 12018 and 12019
- Sup 42 done
- Sup 47 done
- Sup 58 done
- Sup 66 done – overrides version on CIDs 220 thru 242, 3627 from 20030130 to 20030327 though content is the same; overrides version on CID 3015 from 20030108 to 20030327 though content is the same; TID 3509 did not have extensibility specified (made Extensible)
- Sup 67 done
- Sup 71 done
- Sup 72 done
- Sup 73 done
- Sup 75 done
- Sup 76 done
- Sup 77 done - TID 3251 did not have extensibility specified (made Extensible)
- Sup 79 done
- Sup 85 done
- Sup 88 done
- Sup 91 done – including ft2
- Sup 93 done
-
- CP 275 done – was incompletely incorporated in 2003; fix now
- CP 309 done – assigned missing version to CID 7205
- CP 323 done
- CP 326 done
- CP 328 done
- CP 331 done
- CP 339 done
- CP 351 done
- CP 371 done
- CP 372 done
- CP 373 done
- CP 374 done

--`,,,,`,-`-`,,`,,`,`,,`---

Copyright National Electrical Manufacturers Association
Provided by IHS under license with NEMA
No reproduction or networking permitted without license from IHS
Not for Resale

- CP 376 done
- CP 377 done
- CP 386 done – made CIDs 4030 and 4031 into 4032 and 4033 instead, since conflicted with Sup 58 – updated CP FT accordingly
- CP 388 done
- CP 389 done
- CP 390 done
- CP 391 done
- CP 394 done
- CP 396 done
- CP 403 done
- CP 406 done
- CP 418 done
- CP 429 done
- CP 451 done
- CP 453 done
- CP 455 done
- CP 456 done
- CP 458 done
- CP 459 done
-

Part 17

- Created
- Moved PS 3.3 Annexes
- Sup 26 PS 3.3 additions put here instead
- Sup 45 PS 3.4 additions put here instead
- Sup 66 PS 3.3 additions put here instead
- Sup 67 done
- Sup 71 PS 3.3 additions put here instead
- Sup 72 PS 3.3 additions put here instead
- Sup 73 PS 3.3 additions put here instead
- Sup 76 done
- Sup 77 done
- Sup 79 PS 3.3 additions put here instead
- Sup 85 done
- Sup 91 done – including ft2
-
- CP 376 done
- CP 403 done
- CP 418 done
- CP 459 done

Part 18

Copyright National Electrical Manufacturers Association
Provided by IHS under license with NEMA
No reproduction or networking permitted without license from IHS
Not for Resale

- Created
- Sup 85 done

Supplements Incorporated

Sup 26 – OB-GYN Ultrasound Procedure Reports
Sup 42 – MPEG2 Transfer Syntax
Sup 45 – Ultrasound Staged Protocol Data Management
Sup 47 – Visible Light Video
Sup 58 – Enhanced CT Image Storage SOP Class
Sup 64 – Revised Conformance Statements
Sup 66 – Catheterization Lab Structured Reports
Sup 67 – Configuration Management
Sup 71 – Vascular Ultrasound Procedure Reports
Sup 72 – Echocardiography Procedure Reports
Sup 73 – Spatial Registration SOP Classes
Sup 75 – Relevant Patient Information Query Service Class
Sup 76 – Quantitative Arteriography and Ventriculography Structured Reports
Sup 77 – Intravascular Ultrasound (IVUS) Structured Reporting
Sup 79 – Breast Imaging Report Templates
Sup 80 – DVD Media Application Profiles
Sup 82 – 2.3GB 90mm MOD Medium Format and use in US Profiles
Sup 84 – Clarification of Ultrasound Region Calibration
Sup 85 – Web Access to DICOM Persistent Objects (WADO)
Sup 87 – USB and Flash Memory Devices
Sup 88 – Media Creation Management Service Class
Sup 90 – SOP Class Relationship Negotiation
Sup 91 – Ophthalmic Photography Image SOP Classes
Sup 92 – Media Application Profile for Digital Radiographic Images in Dentistry
Sup 93 – Instance Availability Notification

Correction Items Incorporated

- CP 159 – Generalize Therapy Module to Intervention Module
- CP 252 – Define support for Chinese Character Sets
- CP 294 – Clarify SR Container Referenced Content Item
- CP 306 – Support for negative error dose values in Radiotherapy
- CP 307 – Clarification of RT Image Position
- CP 308 – Support for Verification Plans in Radiotherapy
- CP 309 – Query for SOP Instance UID of alternate lossy compressed image
- CP 315 – Add General Anatomy Macros
- CP 323 – Code Meaning for UCUM code value of 1
- CP 326 – Enhance Modality Worklist for NM/PET Workflow, JJ1017, and Coded Contrast

--`,,,,`,-`-`,,`,,`,`,,`---

Copyright National Electrical Manufacturers Association
Provided by IHS under license with NEMA
No reproduction or networking permitted without license from IHS Not for Resale

- CP 328 – Add Related Series Sequence to General Series Module
- CP 329 – Clarification of Usage of Center of Rotation Offset in NM IODs
- CP 330 – Addition of Slice Order Indication for NM IODs
- CP 331 – Revision of View Codes for NM IODs
- CP 332 – Forbid overlays for Samples per Pixel > 1
- CP 333 – Clarify Image Type Value Optionality
- CP 334 – Clarify Need to Create MPPS Discontinuation Reason
- CP 335 – Reorganize Part 3 Section C.17.3
- CP 336 – Clarify Behavior with Duplicate SOP Instances in a Storage Commitment
- CP 337 – Allow Non-cine Multiframe XA and XRF Instances
- CP 338 – Add AES to DICOM TLS Negotiation
- CP 339 – Add Missing Code Definitions to PS 3.16, Annex D
- CP 340 – Add Modification Date and Time to GP-SPS
- CP 341 – Add Spectroscopy Data and Raw Data to signature profiles
- CP 342 – MWL Response Identifier should contain only what was requested
- CP 343 – Add Spectroscopy and Raw Data records to DICOMDIR
- CP 344 – Correct references to the retired Referenced Image Box SOP Class
- CP 346 – Rename Enumerated CIDs as Defined
- CP 347 – Support for characterization of fluence maps in radiotherapy
- CP 348 – Clarify Date/Time Matching with UTC Offsets
- CP 350 – Addition of phase description to NM IODs
- CP 351 – Addition of stress/rest terminology to NM IODs
- CP 353 – Extension of MR Echo Train Length attribute
- CP 354 – Fix PRINTER BUFFER FULL status value
- CP 355 – Clarify SCP/SCU Role Selection
- CP 356 – Correct Acquisition Context Module note in DX IOD
- CP 357 – Add attributes to CT IOD for helical pitch
- CP 358 – Clarify AE Value Representation
- CP 359 – Forbid HAS CONCEPT MOD By-Reference Relationship
- CP 360 – Add higher precision X-ray Dose attributes to XA IOD
- CP 361 – Add Synchronization and DX Detector Modules to XA and XRF IODs
- CP 364 – MR Spatial Saturation Sequence incorrect number of items
- CP 365 – Laterality in Enhanced MR
- CP 366 – Pixel Aspect Ratio inappropriate for enhanced MR images
- CP 367 – Palette Color LUT for enhanced MR images
- CP 368 – Redundant conditions in Acquisition Context
- CP 369 – Missing number of items in Contrast/Bolus Module, MR Diffusion and MR Anatomy Macros, Purpose of Reference Code Sequence
- CP 370 – Wrong VR for LUT Label in Enhanced MR
- CP 371 – Update language and country codes
- CP 372 – Provide coding scheme UIDs
- CP 373 – Correct CID 7455
- CP 374 – Correct View Codes

Copyright National Electrical Manufacturers Association
Provided by IHS under license with NEMA
No reproduction or networking permitted without license from IHS
Not for Resale

- CP 376 – Fix Typos in related to OB-GYN templates
- CP 377 – Support for OB-GYN Vascular Measurements
- CP 378 – Add comparison with ISO-2022-JP-2 for Japanese character sets
- CP 379 – Various MR attribute changes
- CP 380 – Mixed image multi-frame functional group requirements in Enhanced MR
- CP 381 – Defined Terms for Image Type in Enhanced MR
- CP 382 – Clarify Concatenation requirements in Enhanced MR
- CP 383 – MR Spectroscopy Fixes
- CP 385 – Supplemental Palette Color Compression
- CP 386 – MR Chemical Shift in Metabolite Maps
- CP 388 – Update template definition for extensibility
- CP 389 – Add volume measurement to TID 40xx
- CP 390 – Add missing TID 14xx definitions
- CP 391 – Corrections to context groups 6018, 6019
- CP 392 – Add Frame Pointers Module to Multi-Frame US IOD
- CP 394 – Correct Typo in TID 1006
- CP 395 – Addition of slice order indication and View Code Sequence to PET IOD
- CP 396 – Correct TID 4017, 4018, 4020
- CP 397 – Query Key for SOP Classes in Study
- CP 399 – Calibration of Color Displays for Grayscale
- CP 400 – Lossy Compression Method and Original Images
- CP 401 – Patient Orientation
- CP 403 – Fixes to Vascular Templates
- CP 404 – Add defined terms, medium type for Mammography
- CP 405 – Remove the restriction of VOI LUT from the NM IOD
- CP 406 – Add Discontinued Reason Codes to PS3.16 Annex D
- CP 407 – Correct service status classes
- CP 408 – Add 12bit Lossy JPEG to STD-XA1K-DVD
- CP 409 – Add Reason for Requested Procedure Code Sequence
- CP 410 – Correct Observation Datetime condition
- CP 411 – Refine Mammography Positioning Attributes
- CP 412 – Clarify Type in SOP Common Module
- CP 413 – Change documentation of Icon Image Sequence
- CP 417 – Add US Region Bit Flags
- CP 418 – Sup72 Corrections
- CP 420 – Add R-Wave Time Vector
- CP 421 – Add AES to DICOM Secure Media and Attribute Encryption
- CP 422 – Add Issuer of Patient ID to Patient Module
- CP 424 – Clarify specializations of Referenced Image Sequence
- CP 426 – Correct SNOMED codes in CID 4031 and CID 4016
- CP 429 – Use pre-coordinated terms in TID 3507
- CP 431 – Add MR Series Module

--`,,,,`-`-`,,`,,`,`,,`---

Copyright National Electrical Manufacturers Association
Provided by IHS under license with NEMA
No reproduction or networking permitted without license from IHS Not for Resale

- CP 432 – UTC Synchronization Frame of Reference
- CP 433 – Retire Ultrasound Frame of Reference

- CP 268 – Clarify definition of SOP Instance
- CP 269 – Define Media Storage Services
- CP 428 – Add Summary Assessments to TID 3570 and 3812
- CP 435 – Dose Reference UID in RT Plan
- CP 436 – Additional Dose Volume Histogram Type
- CP 437 – RT Control Point Example D
- CP 438 – Fraction Group Description
- CP 439 – Clarification of Structures with Excluded Volumes in RT
- CP 440 – New Defined Terms for Fixation Device Type in RT Setup Module
- CP 441 – RT Alternate Accessory Codes
- CP 442 – RT Tissue Heterogeneity Correction
- CP 443 – RT Wedge Position Clarification
- CP 444 – Clarify the use of Reference Series in Presentation State
- CP 445 – Allows X-Ray Table Module included when only angulation done
- CP 446 – Distance Source to Detector and SID errors
- CP 447 – MR Enhanced Contrast/Bolus Module
- CP 451 – Add Key Object Selection Document Title for Report Attachment
- CP 453 – Define Graphic Type Value Set Constraint
- CP 454 – Correct description of SCOORD Image Reference
- CP 455 – Correct multiplicity in TID 1002
- CP 456 – Correct default value in TID 1006
- CP 458 – Correct condition in TID 1404
- CP 459 – Create PS 3.17 for Explanatory Information

Copyright National Electrical Manufacturers Association
Provided by IHS under license with NEMA
No reproduction or networking permitted without license from IHS
Not for Resale

Copyright National Electrical Manufacturers Association
Provided by IHS under license with NEMA
No reproduction or networking permitted without license from IHS
Not for Resale



NATIONAL ELECTRICAL MANUAFACTURERS ASSOCIATION
1300 NORTH 17TH STREET, SUITE 1847, ROSSLYN, VIRGINIA 22209

Copyright National Electrical Manufacturers Association
Provided by IHS under license with NEMA
No reproduction or networking permitted without license from IHS
Not for Resale