Errata

NFPA 130

Standard for Fixed Guideway Transit and Passenger Rail Systems

2007 Edition

Reference: Table 8.4.1 and 8.4.1.15
Errata No.: 130-07-01

The Committee on Fixed Guideway Transit Systems notes the following error in the 2007 edition of NFPA 130, *Standard for Fixed Guideway Transit and Passenger Rail Systems*.

1. *Revise Table 8.4.1, Function of Material Column, as follows:*
Light Diffusers, windows and transparent plastic windscreens [b, i, ~~m~~]
Delete Note m, as it refers to penetrations acting as passageways for fire and smoke and is not applicable to Light Diffusers.

2. *Revise Table 8.4.1, Category Column, as follows:*
Elastomers [a,~~i~~, j]
Delete Note i, as it refers to combustible signage and is not applicable to Elastomers.

3. *Revise Table 8.4.1, Test Method, Column, for wire and cable as follows:*
See 8.6.8.1.2 ~~8.5.7.1.2~~ through 8.6.8.1.4 ~~8.5.7.1.4~~.
Delete Sections 8.5.7.1.2 and 8.5.7.1.4, as they do not exist. The correct references are Sections 8.6.8.1.2 and 8.6.8.1.4.

4. *Revise Section 8.4.1.15 as follows:*
Replace "Section 8.6" with "Section 8.5".
Section 8.6 refers to Elecrical Fire Safety and is the wrong reference for the floor fire test.

Issue Date: July 10, 2007

Copyright © 2007 All Rights Reserved
NATIONAL FIRE PROTECTION ASSOCIATION

Copyright National Fire Protection Association
Provided by IHS under license with NFPA
No reproduction or networking permitted without license from IHS
Not for Resale