**Errata**

# NFPA 1911

## Standard for the Inspection, Maintenance, Testing, and Retirement of In-Service Automotive Fire Apparatus

**2007 Edition**

**Reference: 22.7.4.2, 22.7.4.3, and 22.7.4.5**
**Errata No.: 1911-07-1**

The Committee on Fire Department Apparatus notes the following error in the 2007 edition of NFPA 1911, *Standard for the Inspection, Maintenance, Testing, and Retirement of In-Service Automotive Fire Apparatus*.

*1. Revise text as follows:*

**22.7.4.2** The power source shall be loaded to 50 percent ±10 percent of the load specified in 22.7.2 ~~22.3.2~~, and the voltage and frequency shall be measured and recorded.

**22.7.4.3** The power source shall be loaded to the load specified in 22.7.2 ~~22.3.2~~, and the voltage and frequency shall be measured and recorded.

**22.7.4.5** The power source shall be unloaded to 50 percent ±10 percent of the load specified in 22.7.2 ~~22.3.2~~, and the voltage and frequency shall be measured and recorded.

**Issue Date:** February 21, 2008

Copyright © 2008 All Rights Reserved
NATIONAL FIRE PROTECTION ASSOCIATION

--`,,```,,,,````-`-`,,`,,`,`,,`---

Copyright National Fire Protection Association
Provided by IHS under license with NFPA
No reproduction or networking permitted without license from IHS

Not for Resale