Errata

NFPA 1971

Standard on Protective Ensembles for Structural Fire Fighting and Proximity Fire Fighting

2007 Edition

Reference: 7.10.17
Errata No.: 1971-07-3

The Committee on Fire Department Apparatus notes the following error in the 2007 edition of NFPA 1971, *Standard on Protective Ensembles for Structural Fire Fighting and Proximity Fire Fighting*.

1. Delete the existing text of 7.10.17 in the current 2007 edition and replace with the text in 7.10.19 as follows:

7.10.17 Footwear shall be tested for resistance to heat as specified in Section 8.6, Heat and Thermal Shrinkage Resistance Test, and shall not have any part of the footwear melt, separate, or ignite; shall show no water penetration; and shall have all components remain functional.

2. Delete existing 7.10.19 in its entirety.

Issue Date: June 18, 2008

(Note: Electronic products and pamphlet reprints may have this errata incorporated. For current information about the NFPA Codes and Standards, including this errata, please see www.nfpa.org/codelist)

Copyright © 2008 All Rights Reserved
NATIONAL FIRE PROTECTION ASSOCIATION

--`,,```,,,,````-`-`,,`,,`,`,,`---

Copyright National Fire Protection Association
Provided by IHS under license with NFPA
No reproduction or networking permitted without license from IHS

Not for Resale