Errata

NFPA 1994

Standard on Protective Ensembles for First Responders to CBRN Terrorism Incidents

2007 Edition

Reference: 7.2.3.5
Errata No.: 1994-07-02

The Committee on Hazardous Materials Protective Clothing and Equipment notes the following error in the 2007 edition of NFPA 1994, *Standard on Protective Ensembles for First Responders to CBRN Terrorism Incidents*.

1. In Section 7.2.3.5 revise the text to read as follows:

7.2.3.5 Class 3 glove materials shall be tested for puncture resistance as specified in Section 8.15, Puncture Resistance Test 1, and shall have a puncture resistance of not less than ~~19~~ 11 N (2.5 lbf).

Issue Date: February 23, 2007

Copyright © 2007 All Rights Reserved
NATIONAL FIRE PROTECTION ASSOCIATION

Copyright National Fire Protection Association
Provided by IHS under license with NFPA
No reproduction or networking permitted without license from IHS
Not for Resale