Errata

NFPA 31

Standard for the Installation of Oil-Burning Equipment

2006 Edition (2001 Edition)

Reference: Figure A.6.7.3
Errata No.: 31-06-01/31-01-1

The Technical Committee on Liquid Fuel Burning Equipment notes the following correction to the 2006 edition and 2001 edition of NFPA 31, *Standard for the Installation of Oil-Burning Equipment*.

In Figure A.6.7.3, the NOTE should read as follows:

NOTE. All distances are measured from the nearest point of the air inlet or draft vent terminal.

Issue Date: March 13, 2006

Copyright © 2006 all Rights Reserved
NATIONAL FIRE PROTECTION ASSOCIATION

Copyright National Fire Protection Association
Provided by IHS under license with NFPA
No reproduction or networking permitted without license from IHS
Not for Resale