Errata

NFPA 31

Standard for the Installation of Oil-Burning Equipment

2006 Edition

Reference: 7.5.9(1)
Errata No.: 31-06-02

The Technical Committee on Liquid Fuel Burning Equipment notes the following correction to the 2006 edition of NFPA 31, *Standard for the Installation of Oil-Burning Equipment*.

1. Paragraph 7.5.9(1) should read as follows:

(1) The tank shall be pitched toward the opening with a slope of not less than 1/4 in. for every 5 ft of length (4 mm/m).

Issue Date: March 26, 2007

Copyright © 2007 All Rights Reserved
NATIONAL FIRE PROTECTION ASSOCIATION

--`,,```,,,,````-`-`,,`,,`,`,,`---

Copyright National Fire Protection Association
Provided by IHS under license with NFPA
No reproduction or networking permitted without license from IHS

Not for Resale