Errata

NFPA 79

Electrical Standard for Industrial Machinery

2007 Edition

Reference: 6.3.1
Errata No.: 79-07-3

The Committee on Electrical Equipment of Industrial Machinery notes the following error in the 2007 edition of NFPA 79, *Electrical Standard for Industrial Machinery*.

6.3.1 General. Protection against indirect contact *(see 3.3.~~18~~19.2)* is intended to prevent hazardous conditions to continue in the event of a fault condition (e.g., insulation failure between live and exposed conductive parts).

Issue Date: April 13, 2009

(Note: Electronic products and pamphlet reprints may have this errata incorporated. For current information about the NFPA Codes and Standards, including this errata, please see www.nfpa.org/codelist)

Copyright © 2009 All Rights Reserved
NATIONAL FIRE PROTECTION ASSOCIATION

Copyright National Fire Protection Association
Provided by IHS under license with NFPA
No reproduction or networking permitted without license from IHS
Not for Resale